




Toyota Rear Third Member Flange Identification

In order to verify what type of pinion seal on the following listed vehicles please refer to the picture below.

2003 and Newer 4runners
2003-2006 Tundra
2003-2006 Sequoia



On the left is a traditional Toyota flange. In an effort to control driveshaft harmonic imbalances Toyota installed these harmonic yokes pictured on right (Thick Rubber infused flanges with Studs versus the Standard thin style with bolt and Nut configuration)